



- SF₆
-
- SF₆ ppm
-
- SF₆
- RS-485

	-50... +30 °C
	1 ... 12 bar
	-40... +80 °C

	+20 °C	1 ... 12 bar
SF ₆	SF ₆ /N ₂	0... 100 kg/m ³
	ppm	40... 40 000 ppm
		-65... +30 °C

	± 3 °C
	< 2 °C / 5
+23 °C	± 0.4 % FS
	± 0.01 bar/10 °C
	< 1 % FS / 5
	0... +40 °C ± 0.5 °C
	-40... 80 °C ± 1 °C

SF ₆	1 ... 12 bara	0... +40 °C ± 1 % FS
		-40... +60 °C ± 2.2 % FS
ppm		± 7 ppm + 15%
5... 1000 ppm	7 bar	

	MPS1
	°

	< 1 s	
63 % [90 %]	¹⁾ 20 °C 1 bar	-50 -10 °C Tdf 5s [10s]

/ 6 q -ð pD4øE Gø PGø

15

CE